AERO® brand aerosols are the finest available anywhere. A full range of solutions, from cleaning, to pest control. No other products can match our standards or our commitment to quality!

HIGHLIGHTS

- Suitable where high temperature may be encountered
- Waterproof, transparent, flexible and non-staining
- Ideal for uneven or porous surfaces & weight materials
- Formulated with the environment in mind

TYPICAL PROPERTIES

• Solids: 18 - 20%

• Odor: Acetone

• Propellant: Hydrocarbon

Spray Characteristics: Web

Net Weight: 12 OZ (341g)

SAFETY CAUTIONS

- Keep out of reach of children
- Contents under pressure. Do not use around sources of ignition such as open flames, pilot lights, etc. Do not store at temperatures above 120°F, or in direct sunlight. Do not puncture or incinerate container. Wrap empty container and put in trash collection.
- Refer to MSDS for additional safety information

HMIS RATINGS

- Health: 2
- Flammability: 4
- Reactivity: 0
- Max. Personal Protection: G





Frank Fabrie Web Adhestre

NON-CHLORINATEDVOC COMPLIANT



Aero® FOAM & FABRIC WEB ADHESIVE is one of the highest performance aerosol adhesives available. For both temporary or permanent bonding. This high solids product is ideal for uneven or porous surfaces and

weight materials. Waterproof, flexible, transparent and non-staining. Use Aero® FOAM & FABRIC WEB ADHESIVE for your toughest adhesive applications with materials such as leather, cardboard, most plastics, polyethylene sheeting and cloth. Formulated with the environment in mind. Aero® FOAM & FABRIC WEB ADHESIVE contains no chlorinated solvents or ozone depleters. Cleans easily with Mineral Spirits. Not intended for use on vinyl.

DIRECTIONS FOR USE

SHAKE WELL BEFORE USING. For best results, hold can 6" to 8" from surface to be bonded and apply uniform coat.

PERMANENT BONDS: Coat both surfaces evenly. Allow 30 seconds dry time before assembly. Bonds should be made while adhesive is wet and tacky.

NON-PERMANENT BONDS: For easy removable applications, apply a light coat to 1 surface and allow to dry at least 5 minutes before mounting. Surfaces can then be separated when desired.

TO CLEAN: Invert can and depress tip up until adhesive is cleared. Clean up over-spray and smears with naphtha or turpentine. Replace cap and store in a cool place, away from direct sunlight.

Distributed by: AERO Chemical Company Atlanta, Georgia 30321